



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000788

DATE: 05-Dec-2014

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	MAX66140K-000AA+	MAX66240ESA+	05-Dec-2014	04-Dec-2016	The part was not released
Discontinuance	MAX66040E-000AA+	MAX66240ESA+	05-Dec-2014	04-Dec-2016	The part was not released
Discontinuance	DS9108-12#	N/A	08-Jun-2015	07-Jun-2017	Part can no longer be manufactured
Discontinuance	DS1921G-F5#A22	N/A	08-Jun-2015	07-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX88921EFD+	N/A	08-Jun-2015	07-Jun-2017	The part was not released
Discontinuance	MAX88130EFD+	N/A	08-Jun-2015	07-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX88921EFD+T	N/A	08-Jun-2015	07-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX2906ETL+TCGEW	MAX2906ETL+TCGE	05-Dec-2014	04-Dec-2016	The part was not released
Discontinuance	DS2714E+	N/A	08-Jun-2015	07-Jun-2017	Part can no longer be manufactured
Discontinuance	DS2434S	N/A	08-Jun-2015	07-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX24021-EVAL-OA	N/A	05-Dec-2014	04-Dec-2016	The part was not released
Discontinuance	MAX24021ETJ+	N/A	05-Dec-2014	04-Dec-2016	The part was not released
Discontinuance	MAX24022ETJ+	N/A	05-Dec-2014	04-Dec-2016	The part was not released
Discontinuance	MAX3791E/D+	N/A	05-Dec-2014	04-Dec-2016	The part was not released
Discontinuance	LMX321AUK	MAX4291EUK+T	08-Jun-2015	07-Jun-2017	Part can no longer be manufactured
Discontinuance	LMX321AUK+T	MAX4291EUK+T	08-Jun-2015	07-Jun-2017	Part can no longer be manufactured
Discontinuance	LMX321AUK-T	MAX4291EUK+T	08-Jun-2015	07-Jun-2017	Part can no longer be manufactured
Discontinuance	LMX321AXK+	MAX9636AXT+T	08-Jun-2015	07-Jun-2017	Part can no longer be manufactured
Discontinuance	LMX358AKA+	MAX9637AXA+T	08-Jun-2015	07-Jun-2017	Part can no longer be manufactured
Discontinuance	LMX358AKA+T	MAX9637AXA+T	08-Jun-2015	07-Jun-2017	Part can no longer be manufactured
Discontinuance	LMX358ASA+	MAX4294ESD+	08-Jun-2015	07-Jun-2017	Part can no longer be manufactured
Discontinuance	LMX358AUA+	MAX4292EUA+	08-Jun-2015	07-Jun-2017	Part can no longer be manufactured
Discontinuance	LMX358AUA+T	MAX4292EUA+T	08-Jun-2015	07-Jun-2017	Part can no longer be manufactured
Discontinuance	LMX324ASD	MAX4294ESD+	08-Jun-2015	07-Jun-2017	Part can no longer be manufactured
Discontinuance	LMX324ASD+T	MAX4294ESD+T	08-Jun-2015	07-Jun-2017	Part can no longer be manufactured
Discontinuance	LMX324AUD+	MAX4294EUD+	08-Jun-2015	07-Jun-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 05-Jan-2015

Discontinuance	LMX324AUD+B3Q	MAX4294EUD+	08-Jun-2015	07-Jun-2017	Part can no longer be manufactured
Discontinuance	LMX321AUK+	MAX4291EUK+T	08-Jun-2015	07-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX11190ETE+	MAX11190ATE+	08-Jun-2015	07-Jun-2017	The part was not released
Discontinuance	MAX339ETE	MAX339ETE+	08-Jun-2015	07-Jun-2017	Part is leaded, and a lead-free replacement exists
Discontinuance	MAX338ETE	MAX338ETE+	08-Jun-2015	07-Jun-2017	Part is leaded, and a lead-free replacement exists
Discontinuance	MAX72024C#	MAX72024C+	08-Jun-2015	07-Jun-2017	Part is leaded, and a lead-free replacement exists
Discontinuance	MAX72038B#	MAX72038B+	08-Jun-2015	07-Jun-2017	Part is leaded, and a lead-free replacement exists
Discontinuance	MAX72463B#	MAX72463B+	08-Jun-2015	07-Jun-2017	Part is leaded, and a lead-free replacement exists
Discontinuance	MAX72466B#	MAX72466B+	08-Jun-2015	07-Jun-2017	Part is leaded, and a lead-free replacement exists
Discontinuance	MAX72950#	MAX72950+	08-Jun-2015	07-Jun-2017	Part is leaded, and a lead-free replacement exists
Discontinuance	MAX72951#	MAX72951+	08-Jun-2015	07-Jun-2017	Part is leaded, and a lead-free replacement exists
Discontinuance	MAX72952#	MAX72952+	08-Jun-2015	07-Jun-2017	Part is leaded, and a lead-free replacement exists
Discontinuance	DS2404-001+	DS2417P+T&R	08-Jun-2015	07-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX72018C#	MAX72018C+	08-Jun-2015	07-Jun-2017	Part is leaded, and a lead-free replacement exists
Reactivation	DS91230+	DS91230+	05-Dec-2014	04-Dec-2016	Reactivation
Discontinuance	DS9106S-0G0+	N/A	05-Dec-2014	04-Dec-2016	Part can no longer be manufactured
Discontinuance	DS1921G-F5#A0C	N/A	08-Jun-2015	07-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX24022-EVAL-OA	N/A	05-Dec-2014	04-Dec-2016	The part was not released
Discontinuance	ICM7217JI	ICM7217JI+	07-Dec-2015	06-Dec-2017	Part is leaded, and a lead-free replacement exists
Discontinuance	LMX321AXK+T	MAX9636AXT+T	08-Jun-2015	07-Jun-2017	Part can no longer be manufactured
Discontinuance	LMX358ASA+T	MAX4292ESA+T	08-Jun-2015	07-Jun-2017	Part can no longer be manufactured
Discontinuance	LMX324ASD+	MAX4294ESD+	08-Jun-2015	07-Jun-2017	Part can no longer be manufactured
Discontinuance	LMX324AUD+T	MAX4294EUD+T	08-Jun-2015	07-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5422ETA	MAX5422ETA+	08-Jun-2015	07-Jun-2017	Part is leaded, and a lead-free replacement exists
Discontinuance	MAX72044B#	MAX72044B+	08-Jun-2015	07-Jun-2017	Part is leaded, and a lead-free replacement exists
Discontinuance	DS9108-10#	N/A	08-Jun-2015	07-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5424ETA	MAX5424ETA+	08-Jun-2015	07-Jun-2017	Part is leaded, and a lead-free replacement exists
Discontinuance	MAX66140E-000AA+	MAX66240ESA+	05-Dec-2014	04-Dec-2016	The part was not released
Discontinuance	MAX66040K-000AA+	MAX66240ESA+	05-Dec-2014	04-Dec-2016	The part was not released
Discontinuance	DS1922L-F5#A20	N/A	08-Jun-2015	07-Jun-2017	Part can no longer be manufactured