



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000798

DATE: 21-Mar-2015

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	MAX5880XUXF+W	N/A	21-Sep-2015	20-Sep-2017	Part can no longer be manufactured
Discontinuance	MAX5880YUXF+W	N/A	21-Sep-2015	20-Sep-2017	Part can no longer be manufactured
Discontinuance	DS3908N+T&R	N/A	21-Sep-2015	20-Sep-2017	Part can no longer be manufactured
Discontinuance	DS3908N-001+	N/A	21-Sep-2015	20-Sep-2017	Part can no longer be manufactured
Discontinuance	MAX4270ESD	N/A	21-Sep-2015	20-Sep-2017	Part can no longer be manufactured
Discontinuance	MAX4292EBL	N/A	21-Sep-2015	20-Sep-2017	Part can no longer be manufactured
Discontinuance	MAX4362ESD+	N/A	21-Sep-2015	20-Sep-2017	Part can no longer be manufactured
Discontinuance	MAX44244AUK+T	N/A	21-Sep-2015	20-Sep-2017	Part can no longer be manufactured
Discontinuance	MAX44245ASD+T	N/A	21-Sep-2015	20-Sep-2017	Part can no longer be manufactured
Discontinuance	MAX2143CEGH/V+TCCK	MAX2143DEGH/V+TCCK	21-Sep-2015	20-Sep-2017	Part can no longer be manufactured
Discontinuance	MAX2151ETJ/V+	MAX2151BETJ/V+	21-Sep-2015	20-Sep-2017	Part can no longer be manufactured
Discontinuance	MAX2151ETJ/V+T	MAX2151BETJ/V+T	21-Sep-2015	20-Sep-2017	Part can no longer be manufactured
Discontinuance	MAX77817AEWV+	N/A	21-Mar-2015	21-Mar-2017	The part was not released
Discontinuance	MAX9644EBS+TG45	N/A	21-Sep-2015	20-Sep-2017	Part can no longer be manufactured
Discontinuance	MAX9645EBS+TG45	N/A	21-Sep-2015	20-Sep-2017	Part can no longer be manufactured
Discontinuance	MAX77817AEWV+T	N/A	21-Mar-2015	21-Mar-2017	The part was not released
Discontinuance	MAX77817EVKIT#	N/A	21-Mar-2015	21-Mar-2017	The eval kit is no longer supported
Discontinuance	MAX77817EWW+	N/A	21-Mar-2015	21-Mar-2017	The part was not released
Discontinuance	MAX77817EWW+T	N/A	21-Mar-2015	21-Mar-2017	The part was not released
Discontinuance	ICL7109MJL	N/A	21-Sep-2015	20-Sep-2017	Part can no longer be manufactured
Discontinuance	MAX9967BGCCQ+D	MAX9967BRCCQ+D	21-Sep-2015	20-Sep-2017	Part can no longer be manufactured
Discontinuance	DS1804U-100	DS1804U-100+	21-Sep-2015	20-Sep-2017	Part is leaded, and a lead-free replacement exists
Discontinuance	DS1821C+	DS18B20+	20-Sep-2016	20-Sep-2018	Part can no longer be manufactured
Discontinuance	DS1821S+	DS18B20Z+	20-Sep-2016	20-Sep-2018	Part can no longer be manufactured
Discontinuance	DS1821S+T&R	DS18B20Z+T&R	20-Sep-2016	20-Sep-2018	Part can no longer be manufactured
Discontinuance	DS1821S-C05+T&R	DS18B20Z+T&R	20-Sep-2016	20-Sep-2018	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 21-Apr-2015

Discontinuance	MAX3693EVKIT	N/A	21-Mar-2015	21-Mar-2017	The eval kit is no longer supported
Discontinuance	MAX14691ETP+T	MAX14691ATP+T	21-Sep-2015	20-Sep-2017	The part was not released
Discontinuance	MAX14692ETP+T	MAX14692ATP+T	21-Sep-2015	20-Sep-2017	The part was not released
Discontinuance	MAX2906ETL+	MAX2906ETL/V+	21-Sep-2015	20-Sep-2017	Part can no longer be manufactured
Discontinuance	MAX2906ETL+T	MAX2906ETL/V+T	21-Sep-2015	20-Sep-2017	Part can no longer be manufactured
Discontinuance	ICL7109IJL	N/A	21-Sep-2015	20-Sep-2017	Part can no longer be manufactured
Discontinuance	MAX9967ADCCQ+D	MAX9967BRCCQ+D	21-Sep-2015	20-Sep-2017	Part can no longer be manufactured
Discontinuance	MAX5880PUXF+W	N/A	21-Sep-2015	20-Sep-2017	Part can no longer be manufactured